



Dolby Voice Room 5.0.1

Release notes

10 July 2020

1 Introduction

This document provides information about the Dolby Voice Room 5.0.1 release, including the latest product features, bug fixes, known issues, and upgrade instructions.

See the Dolby Voice Room Quick Start Guide v5.0 and Dolby Voice Room Administrator's Guide for detailed product specifications and operating instructions.

2 New Features

Table 1: Features introduced in this release

Dolby Reference	Summary
DVHH-4130	Added support for Microsoft Teams interoperability via Poly RealConnect gateway

Table 2: Features introduced in the 5.0.0 release

Dolby Reference	Summary
DVHH-304	Added BLE advertising API in DAPI
DVHH-3207	Added initial support for installed rooms with USB as both audio input and output devices only
DVHH-3919	Added an option to disable content share during SIP video calls

3 Fixes

Table 3: Fixes introduced in this release

Dolby Reference	Summary
DVHH-4162	Dolby Voice Room does not work with third-party cameras
DVHH-4167	During SIP video meetings content received may show video artifacts in impaired network environments

Table 4: Fixes introduced in the 5.0.0 release

Dolby Reference	Summary
DVHH-3289	Enabled TLS certification name validation when dialed by IP address
DVHH-3226	Added parameters to convey HDMI Input audio stream status
DVHH-3038	Removed expiring CA certificates
DVHH-3295	Added support to disable voice assistant during the listening state in the middle of an active call mutes the microphone
DVHH-3881	Constant active speaker notifications when HDMI input is used but no audio is being played

Table 4: Fixes introduced in the 5.0.0 release (continued)

Dolby Reference	Summary
DVHH-4108	Added support for a wildcard in Subject Alternate Name validation for TLS SIP calls
DVHH-4147	Added Brisbane in the GMT+10 timezone

4 Notes

Please refer to the configuration reference material in the Dolby Voice Room Administrator's Guide v5.0 for updated configuration parameters supporting new features.

5 Known Issues

Table 5: Known Issues present in this release

Dolby Reference	Summary	Significance/Impact	Workaround
N/A	N/A	N/A	N/A

6 Installation and Upgrade Procedure

The procedure described in the section titled “Updating the Dolby Voice Room software” of the Dolby Voice Room Administrator's Guide v5.0 should be followed to install or upgrade to the firmware in this release.

Notices

Copyright

© 2020 Dolby Laboratories. All rights reserved.

Dolby Laboratories, Inc.

1275 Market Street
 San Francisco, CA 94103-1410 USA
 Telephone 415-558-0200
 Fax 415-645-4000
<http://www.dolby.com>

Trademarks

Dolby and the double-D symbol are registered trademarks of Dolby Laboratories.

The following are trademarks of Dolby Laboratories:

Dialogue Intelligence™
 Dolby®
 Dolby Advanced Audio™
 Dolby Atmos®
 Dolby Audio™

Dolby Theatre®
 Dolby Vision®
 Dolby Vision IQ™
 Dolby Voice®
 Feel Every Dimension™

Dolby Cinema®
Dolby Digital Plus™
Dolby Digital Plus Advanced Audio™
Dolby Digital Plus Home Theater™
Dolby Home Theater®

Feel Every Dimension in Dolby™
Feel Every Dimension in Dolby Atmos™
MLP Lossless™
Pro Logic®
Surround EX™

All other trademarks remain the property of their respective owners.

Patents

THIS PRODUCT MAY BE PROTECTED BY PATENTS AND PENDING PATENT APPLICATIONS IN THE UNITED STATES AND ELSEWHERE. FOR MORE INFORMATION, INCLUDING A SPECIFIC LIST OF PATENTS PROTECTING THIS PRODUCT, PLEASE VISIT <http://www.dolby.com/patents>.