



Dolby Conference Phone 4.3.2

Release Notes

14 October 2019

1 Introduction

This document provides information about the Dolby Conference Phone 4.3.2 release, including the latest product features, bug fixes, known issues, and upgrade instructions.

See the *Dolby Conference Phone Administrator's Guide v4.3* and *Dolby Conference Phone User's Guide* for detailed product specifications and operating instructions.

2 New Features

Table 1: Features introduced in this release

Dolby Reference	Summary
N/A	N/A

Table 2: Features introduced in release 4.3.1

Dolby Reference	Summary
N/A	N/A

Table 3: Features introduced in the 4.3.0 release

Dolby Reference	Summary
DCEP-4280	Added support for Syslog Notification API
DCEP-4286	Changed physical mute button operation to accommodate voice assistant interactions
DCEP-4310	Added additional ATS (Amazon Trust Service) certificates
DCEP-4313	Support for touch controller simulator
DCEP-4316	Added "Settings and diagnostics" menu to the reset to factory default overlay
DCEP-4348	DNS, DNS2, and LLDP settings can be provisioned using a provisioning server

3 Fixes

Table 4: Fixes introduced in this release

Dolby Reference	Summary
N/A	N/A

Table 5: Fixes introduced in release 4.3.1

Dolby Reference	Summary
DCEP-4445	In huddle conference room installations, audio does not work when the Dolby Conference Phone uses static IP settings in specific network setups

Table 6: Fixes introduced in the 4.3.0 release

Dolby Reference	Summary
DCEP-4095	By default SSLv3 is disabled
DCEP-4143	PGi GlobalMeet call gets disconnected after ignoring incoming PBX call
DCEP-4302	In attached mode, the Dolby Conference Phone is stuck while upgrading due to low memory
DCEP-4318	Discontinued iLBC codec support for the Dolby Conference Phone
DCEP-4333	802.1x screen displays at reboot when 802.1x is disabled
DCEP-4399	Added Starfield Services Root Certificate Authority - G2 and removed Starfield Class 2 Certification Authority
DCEP-4407	Added LetsEncrypt root certificate authority to default certificate authority bundle

4 Notes

This is a companion release to Dolby Voice Room release 3.0.2.

Please refer to the configuration reference material in the *Dolby Conference Phone Administrator's Guide* v4.3 for updated configuration parameters supporting new features.

5 Known Issues

Table 7: Known Issues present in this release

Dolby Reference	Summary	Significance/Impact	Workaround
N/A	N/A	N/A	N/A

6 Installation and Upgrade Procedure

The procedure described in the section titled “Upgrading and Downgrading the Software on the Dolby Conference Phone” of the *Dolby Conference Phone Administrator's Guide* v4.3 should be followed to install or upgrade to the firmware in this release.

7 Notices

7.1 Copyright

© 2019 Dolby Laboratories. All rights reserved.

Dolby Laboratories, Inc.

1275 Market Street

San Francisco, CA 94103-1410 USA

Telephone 415-558-0200

Fax 415-645-4000

<http://www.dolby.com>

7.2 Trademarks

Dolby and the double-D symbol are registered trademarks of Dolby Laboratories.

The following are trademarks of Dolby Laboratories:

Dialogue Intelligence™

Dolby®

Dolby Advanced Audio™

Dolby Atmos®

Dolby Audio™

Dolby Cinema™

Dolby Digital Plus™

Dolby Digital Plus Advanced Audio™

Dolby Digital Plus Home Theater™

Dolby Home Theater®

Dolby Theatre®

Dolby Vision™

Dolby Voice®

Feel Every Dimension™

Feel Every Dimension in Dolby™

Feel Every Dimension in Dolby Atmos™

MLP Lossless™

Pro Logic®

Surround EX™

All other trademarks remain the property of their respective owners.

7.3 Patents

THIS PRODUCT MAY BE PROTECTED BY PATENTS AND PENDING PATENT APPLICATIONS IN THE UNITED STATES AND ELSEWHERE. FOR MORE INFORMATION, INCLUDING A SPECIFIC LIST OF PATENTS PROTECTING THIS PRODUCT, PLEASE VISIT <http://www.dolby.com/patents>.