



Dolby Conference Phone 4.5.3

Release Notes

18 June 2020

1 Introduction

This document provides information about the Dolby Conference Phone 4.5.3 release, including the latest product features, bug fixes, known issues, and upgrade instructions.

See the *Dolby Conference Phone Administrator's Guide v4.5* and *Dolby Conference Phone User's Guide* for detailed product specifications and operating instructions.

2 New Features

Table 1: Features introduced in this release

Dolby Reference	Summary
N/A	N/A

Table 2: Features introduced in the 4.5.2 release

Dolby Reference	Summary
DCEP-4504	Updated trusted CA certificate list

Table 3: Features introduced in the 4.5.1 release

Dolby Reference	Summary
N/A	N/A

Table 4: Features introduced in the 4.5.0 release

Dolby Reference	Summary
DCEP-4487	Update Dolby Conference Phone to support stream HDMI input audio feature on Dolby Voice Room

3 Fixes

Table 5: Fixes introduced in this release

Dolby Reference	Summary
N/A	N/A

Table 6: Fixes introduced in the 4.5.2 release

Dolby Reference	Summary
N/A	N/A

Table 7: Fixes introduced in the 4.5.1 release

Dolby Reference	Summary
N/A	N/A

Table 8: Fixes introduced in the 4.5.0 release

Dolby Reference	Summary
N/A	N/A

4 Notes

This is a companion release to Dolby Voice Room release 4.1.3. Updates to the Dolby Conference Phone software are to support Dolby Voice Room features and do not add any new features to the Dolby Conference Phone in standalone mode. For more information, please refer to the *Dolby Voice Room Release Notes*.

Please refer to the configuration reference material in the *Dolby Conference Phone Administrator's Guide* v4.5 for updated configuration parameters supporting new features.

5 Known Issues

Table 9: Known Issues present in this release

Dolby Reference	Summary	Significance/Impact	Workaround
N/A	N/A	N/A	N/A

6 Installation and Upgrade Procedure

The procedure described in the section titled “Upgrading and Downgrading the Software on the Dolby Conference Phone” of the *Dolby Conference Phone Administrator's Guide* v4.5 should be followed to install or upgrade to the firmware in this release.

Notices

Copyright

© 2020 Dolby Laboratories. All rights reserved.

Dolby Laboratories, Inc.

1275 Market Street
San Francisco, CA 94103-1410 USA
Telephone 415-558-0200
Fax 415-645-4000
<http://www.dolby.com>

Trademarks

Dolby and the double-D symbol are registered trademarks of Dolby Laboratories.

The following are trademarks of Dolby Laboratories:

Dialogue Intelligence™	Dolby Theatre®
Dolby®	Dolby Vision®
Dolby Advanced Audio™	Dolby Vision IQ™
Dolby Atmos®	Dolby Voice®
Dolby Audio™	Feel Every Dimension™
Dolby Cinema®	Feel Every Dimension in Dolby™
Dolby Digital Plus™	Feel Every Dimension in Dolby Atmos™
Dolby Digital Plus Advanced Audio™	MLP Lossless™
Dolby Digital Plus Home Theater™	Pro Logic®
Dolby Home Theater®	Surround EX™

All other trademarks remain the property of their respective owners.

Patents

THIS PRODUCT MAY BE PROTECTED BY PATENTS AND PENDING PATENT APPLICATIONS IN THE UNITED STATES AND ELSEWHERE. FOR MORE INFORMATION, INCLUDING A SPECIFIC LIST OF PATENTS PROTECTING THIS PRODUCT, PLEASE VISIT <http://www.dolby.com/patents>.